

[illegible][illegible]





FIG. 3b

10057670 042503

Section of the vessel with internal finned Heat exchanger




FIG. 3c

4/18




FIG. 3d

5/18




FIG. 4

6/18





FIG. 5

20527610.0192500T

7/18




FIG. 6

8/18




FIG. 7




FIG. 8



9/18




FIG. 9

10/18




FIG. 10

1005750.042503

11/18




FIG. 11

FIG. 12a




FIG. 12b




FIG. 12c




FIG. 13

13/18




FIG. 14a




FIG. 14b

14/18




FIG. 15a




FIG. 15b

15/18




FIG. 15c




FIG. 15d

20250710.012503




FIG.16a




FIG.16b

40057540-012502



17/18




FIG. 17a




FIG. 17b




FIG. 18a




FIG. 18b




FIG. 18c




FIG. 18d




FIG. 18e




FIG. 18f

4005610.01.23.2023

18/18




FIG. 19a




FIG. 19b




FIG. 20